

KQP 000



Repair completed

Name of Company carrying out the repair: Hdps

Generator Number:	2212	Date:	03/11/2025
-------------------	------	-------	------------

Repair By:	fleet.service	Location:	CHCH
------------	---------------	-----------	------

Hours Run:	8403.00Hrs	Fuel Level:	Full
------------	------------	-------------	------

Generator Back in service date:	04/11/2025
---------------------------------	------------

Repair carried out:

Found rhs shroud bent/remove and straighten

Cabinet loom not secure /open tighten nut secure

This alternator is making a vibration noise it is not affecting it efficientl