

KQP 000



Repair completed

Name of Company carrying out the repair: HDPS Christchurch

Generator Number: 4044

Date: 15/06/2026

Repair By: fleet.service

Location: CHCH

Hours Run: 4858.00Hrs

Fuel Level: Full

Generator Back in service date: 15/06/2026

Repair carried out:

All fuel tank straps broken/ missing. Fuel tank moving inside generator housing and rubbing on engine mount.

Advised to place blocks inside generator to prevent the fuel tank from moving.

Aligned fuel tank to the centre. Placed blocks on all sides to secure fuel tank from sliding around inside the generator.