

KQP 000



Repair completed

Name of Company carrying out the repair: HDPS

Generator Number: 3061

Date: 27/08/2026

Repair By: fleet.service

Location: CHCH

Hours Run: 6973.00Hrs

Fuel Level: Full

Generator Back in service date: 27/08/2026

Repair carried out:

Carried out 750 hour service

Tightened loose fan shroud bolts