

KQP 000



McKay



Repair completed

Name of Company carrying out the repair: Hdps

Generator Number:	3101	Date:	20/11/2025
Repair By:	fleet.service	Location:	CHCH
Hours Run:	4061.00Hrs	Fuel Level:	Full
Generator Back in service date:	21/11/2025		

Repair carried out:

1. Remove rear x member/weld in broken section lhs/refitted, bolt down alternator
2. Batteries removed/remove battery box prep weld crack/refitted battery box, Batteries
3. Tighten rear frame panel bolts, refitted rear panel.