

KQP 000



## Repair completed

Name of Company carrying out the repair: Hdps

Generator Number: 4072

Date: 08/01/2026

Repair By: fleet.service

Location: CHCH

Hours Run: 3200.00Hrs

Fuel Level: Full

Generator Back in service date: 12/01/2026

Repair carried out:

1. Removed belt and tensioner remove/replace bushes in tensioner reassemble to engine fit new belt. Had replaced bushes and bearings on this tensioner