

KQP 000



Repair completed

Name of Company carrying out the repair: Hdps

Generator Number: 3061

Date: 02/02/2026

Repair By: fleet.service

Location: CHCH

Hours Run: 6593.00Hrs

Fuel Level: Full

Generator Back in service date: 02/02/2026

Repair carried out:

1. Removed rear cover and bottom steel plate tank cover
2. Removed old silicone straighten plate ,clean both surfaces and silicone/secure refit top cover