

KQP 000



Repair completed

Name of Company carrying out the repair: Hdps

Generator Number: 4072

Date: 27/02/2026

Repair By: fleet.service

Location: CHCH

Hours Run: 3305.00Hrs

Fuel Level: 0.5

Generator Back in service date: 10/03/2026

Repair carried out:

1. Replace seals on push rod tubes
2. Replace Exhaust manifold gaskets
3. Repair broken steel section of air box frame/weld cracks and add Xtra steel plate in give strength