

KQP 000



Repair completed

Name of Company carrying out the repair: Hdps

Generator Number: 4044

Date: 10/03/2026

Repair By: fleet.service

Location: CHCH

Hours Run: 4679.00Hrs

Fuel Level: Full

Generator Back in service date: 16/03/2026

Repair carried out:

1. Push rod tubes seals replace
2. Exhaust manifold gaskets replace/broken intake manifold studs.studs Replace studs and intake manifold gaskets

3. Air box frame cracked, remove and weld and replace broken steel sections