

KQP 000



Repair completed

Name of Company carrying out the repair: Hdps

Generator Number: 3101

Date: 08/04/2026

Repair By: fleet.service

Location: CHCH

Hours Run: 4464.00Hrs

Fuel Level: Empty

Generator Back in service date: 08/04/2026

Repair carried out:

1. 500hr service
2. Cross member cracked Lhs, remove batteries, support alternator, remove/repair Cross member
3. Fit Cross member reassemble ,milled holes on alternator under side mount so can bolt down into rubber mounts
4. Fuel low