

KQP 000



Repair completed

Name of Company carrying out the repair: HDPS

Generator Number: 3033

Date: 02/09/2026

Repair By: fleet.service

Location: CHCH

Hours Run: 6604.00Hrs

Fuel Level: 0.75

Generator Back in service date: 02/09/2026

Repair carried out:

Radiator blocked- removed and cleaned radiator.

Fuel leak from fuel filter fitting- replaced seals and tightened fitting.

Battery negative post loose inside battery. Replaced batteries