KQP 000

McKay

KiwiRail

Repair completed

Name of Company carrying out the repair:	Heavy Diesel Dynamics		
Generator Number:	GEN4085	Date:	31/03/2025
Repair By:	jonathan.gatman	Location:	HAM
Hours Run:	5716.00Hrs	Fuel Level:	0.25
Generator Back in service date:			

Repair carried out:

Travel to CT site and locate generator. Fault code showing there is no oil pressure. Fitted oil pressure tester and run generator up. oil pressure is fine. Ordered new oil pressure sender. Collected new sender and fit to generator. Run generator up. still faulting. Checked all fuses and wiring. Organize electrician to come check all wiring and main comms board. Found fault in comms board not registering oil pressure. Advised Stephen of fault and is getting generator sent to Auckland.